


TH350 forward clutch drum and input shaft assembly



This distance influences
on front end play ?



0.010'-0.012' between these two rotating plans
Is allright ? Or too much ?