



# REGULAR PRODUCTION OPTION (RPO) WITH GAUGES INSTRUMENT CLUSTER LAYOUT & TRACE RUNS



## INSTRUMENT TESTER:



VARIABLE RESISTOR  
 VALUE NOT IMPORTANT  
 BUT SHOULD BE ABLE  
 TO ADJUST AROUND 100  
 OHMS

